

**ACTON •
MICKELSON •
ENVIRONMENTAL, INC.**

5175 Hillsdale Circle #100
El Dorado Hills, CA 95762

LOG OF BORING

MW-5.10

Facility: G-P Fort Bragg

Address: 90 W. Redwood Ave.
Fort Bragg, CA

AME Project No.: 16017.08

Area No./ Description: Parcel 5, West of Mobile Equipment Shop Building

Page 1 of 1

Drilling Company: RSI
Drilled By: Don Jenkins
Drilling Method: Hollow Stem
Boring Diameter: 8"
Sampling Method: California Modified Split Spoon Sampler

Location (East/North):
Ground Surface Elevation:
Water Depth (Date, Time): 5' (11/16/05 1250)
Casing Elevation:
Total Depth (feet): 14.5' BGS
Weather: sunny/warm

Drilling Started: 11/16/05 1442
Drilling Finished: 11/16/05 1510

Logged By: J.D. Matthey, R.G., C.E.G
Checked By:

Source: Original field notes

PID/FID: PID

DEPTH (feet)	SAMPLE		BLOW COUNTS		SOIL DESCRIPTION	GRAPHIC LOG	SOIL CLASS	WELL GRAPHIC	COMMENTS	FIELD PID READING (ppm)
	INTERVAL	SAMPLE ID	BLOWS/6 IN. (N)	IN. RECD/D					DRILLING RATE AND CONDITIONS, WATER DEPTH, BACKFILL	
0										
		MW-5.10-1.5	16-11-10 (21)	12	FILL - SILTY SAND (SM), dark gray (2.5Y N4/), Medium Dense, Moist, Wood Fragments 20% fine gravel, 0.5 cm clast, 60% fine to medium sand, 20% fines.		SM		12:43	0
5		MW-5.10-5.5	2-2-4 (6)	14	gray (2.5Y 6/1), Medium Dense, Wet, Fill?, Well Sorted, Subrounded to Subangular, Mainly Quartz and Feldspar 80% fine sand, 20% fines.				12:50	0
10			12-17-18 (35)	16	Strong Hydrocarbon Odor.					
									Boring Terminated Total Depth = 14.5'	